

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection: Company Dana Shepherd Field Technician/Draftsman OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0150032	
Inspection Type:	COMPLETE	
Inspection Date:	Tuesday, March 06, 2007	
Start Date/Time:	3/6/2007 9:30:00 AM	
End Date/Time:	3/6/2007 2:00:00 PM	
Last Inspection:	Tuesday, February 06, 2007	

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Cloudy, Temp 42 Deg. F.</u> InspectionID Report Number: <u>1230</u>

Accepted by: pgrubaug

3/22/2007

Permitee: GENWAL RESOURCES INC
Operator: GENWAL RESOURCES INC
Site: CRANDALL CANYON MINE

Address: PO BOX 1077, PRICE UT 84501

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

6,235.80	Total Permitted		
10.70	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership Types of Operations

✓ Federal ✓ Underground

State Surface

County Loadout

Fee Processing

Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

A midterm review of the Crandall Canyon Mine Permit C/015/0032 is currently in progress.

Inspector's Signature:

Hayl A. Mushuse

Date

Tuesday, March 06, 2007

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150032 Inspection Type: COMPLETE

Inspection Date: Tuesday, March 06, 2007

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		~	
2.	Signs and Markers	V		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches	✓	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V	✓		
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	V			
11.	Contemporaneous Reclamation	V			
12.	Backfilling And Grading	V			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.a	Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	✓			
20.	Air Quality Permit	✓		V	
21.	Bonding and Insurance	✓		V	
22.	Other				

Permit Number: C0150032 Inspection Type: COMPLETE

Inspection Date: Tuesday, March 06, 2007

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit is effective 05/10/2005 and expires 05/13/2008. Other documents include the following:

- ·Certificate of Insurance issued 07/01/2006 and terminates 07/01/2007.
- ·Reclamation agreement is dated April 1998 and is signed by both parties.
- UPDES permit UT000024368 effective 12/01/2005 and expires midnight 11/30/2008.
- Air Quality permit DAQE-AN0225003-03, issued 03/20/2003.
- ·SPCC Plan dated 09/18/2004.

2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. All other signs and markers observed during the inspection met the coal rules.

3. Topsoil

A portion of silt fence around the topsoil pile at the entrance to the USFS access road has collapsed. The silt fence needs to be maintained.

4.a Hydrologic Balance: Diversions

The drop inlet structures by the road entrance and adjacent to the crusher building are functional, but need maintenance to prevent them from plugging.

This inlet has been identified in previous inspections as a potential problem. Because of the proximity of the inlet to the permit boundary if the culvert were to plug the drainage could leave the permit area. It would be prudent to perform regular preventative maintenance to prevent the inlet from plugging even though the inlet is still in compliance.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond was last inspected on November 27, 2006. This inspection was performed by a registered P.E. in Utah. The inspection is for the fourth quarter 2006 and annual 2006. The inspection report was P.E. dated, stamped, and signed.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2006 water monitoring is in the EDI website, but has not been uploaded. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

The November and December 2006 Discharge Monitoring Reports were reviewed. Outfall 001 did not discharge either month. Outfall 002 discharged both months, but did not exceed any parameters.

Inspection Continuation Sheet

Permit Number: C0150032 Inspection Type: COMPLETE

Inspection Date: Tuesday, March 06, 2007

Page 4 of 4

8. Noncoal Waste

Noncoal waste items are spread throughout the entire mine site. Lenience was shown since the mine is just coming out of winter conditions; however, the entire mine site shows a lack of attention and maintenance. If the condition persists, enforcement action will be taken.

20. Air Quality Permit

Approval Order DAQE-827-01 was modified on March 20, 2003. This modification allowed additional coal handling equipment (conveyors) for the South Crandall Portals. The new approval order, DAQE-AN0225003-03, was effective March 20, 2003.

21. Bonding and Insurance

Insurance is provided through Federal Insurance Co. policy #3710-95-29. The policy meets the minimum coverage requirements, has explosive coverage, contains the proper language in the notification clause, and shows the State of Utah as the certificate holder.

The bonded amount for the Crandall Canyon Mine is \$1,654,000, bond #14-96-15.